MAXANT

HONEY PROCESSING EQUIPMENT

3100 Leg Kit Instructions

FOR ALL 3100 SERIES EXTRACTORS MANUFACTURED IN 2009+

THE LUGS ON THE BOTTOM RING OF YOUR 3100 SERIES EXTRACTOR HAVE BEEN WELDED IN FIXTURES PRECISELY AT 120 DEGREES.

STEP 1

REMOVE ALL HARDWARE FROM YOUR PACKAGE. THE 3 CARRIAGE BOLTS ARE USED FOR THE LEG TO HOOP. THE 3 HEX BOLTS ARE USED FOR EXTRACTOR LUG TO TOP LEG.

STEP 2

INSERT CARRIAGE BOLT ON OUTER LEG THROUGH THE LEG HOOP, THEN ATTACH FLAT WASHER, AND LOCK WASHER ON INNER LEG HOOP. HAND-TIGHTEN BOLT ON UNTIL ALL 3 LEGS ARE ATTACHED. YOU MAY NEED TO MOVE THE LEG A LITTLE TO LINE UP WITH THE EXTRACTOR LUG TO LEG HOLES.

STEP 3

NEXT, TAKE YOUR EXTRACTOR AND LINE LUGS UP WITH LEG SLOTS.

STEP 4

NOW TAKE YOUR 5/16 BOLTS WITH A FLAT WASHER AND INSERT INTO LUG TO LEG HOLE. INSERT LOCK WASHER AND NUT AND TIGHTEN. AFTER ALL 3 TOP BOLTS ARE TIGHT YOU MAY THEN TIGHTEN THE CARRIAGE BOLTS.



If you have any questions or concerns feel free to contact us at:

www.maxantindustries.com • sales@maxantindustries.com

978-772-0576 or 978-772-BEES (2337)

978-772-6365 (fax)

Mail: P.O. Box 454. Aver. MA 01432 Ship: 58 Barnum Rd. Devens. MA 01434